



3RD Angle Projection





Connecting
Auto Transformer (Variac®)
to mains supply

"CORRECT" method of connecting
Auto Transformer (Variac®)
to mains supply



"INCORRECT" Hazardous & Potentially Fatal
method of connecting
Auto Transformer (Variac®)
to mains supply



Auto Transformer
Method of Connection

51 Ferndale Road REVESBY 2212

Drawn By : TRHolder
Date : 05/12/2017

Scale: 1:1

120808-2

A3